

10/016, A 73

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,758,610 B2  
DATED : July 6, 2004  
INVENTOR(S) : Ziari et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7.

Line 54, "said molder is" should read -- said solder is --

Column 8.

Line 22, "of claim wherein" should read -- of claim 22 wherein --

Line 25, "one wide connected" should read -- one side connected --

Line 51, "submount comprise a" should read -- submount comprises a --

Column 10.


Line 15, "said molder" should read -- said solder --

Line 20, "at learnt one" should read -- at least one --

Line 25, "of claim 36" should read -- of claim 37 --

Signed and Sealed this

Nineteenth Day of April, 2005



JON W. DUDAS  
Director of the United States Patent and Trademark Office